





The Impact of System Configuration on Device Radiation Damage Testing of Optical Components

S.D. Kniffin,¹ R.A. Reed,² P.W. Marshall,³ J.W. Howard,⁴ H.S. Kim⁴, J.P. Schepis²

- 1. NASA/Orbital Sciences Corporation, Dulles, VA 20166
- 2. NASA/Goddard Space Flight Center, Greenbelt, MD 20771
 - 3. Consultant, Brookneal, VA 24528
 - 4. NASA/Jackson and Tull, Washington, D.C. 20018

The Authors would like to thank:
The Defense Threat Reduction Agency under IACRO 02-4039I
and the NASA Electronics Parts and Packaging Program
for their support in this investigation





Outline


- Wide Field/Planetary Camera 2 (WF/PC 2)
 Mission and Background
- Operational Anomaly in LED PT Encoder
- Investigation
 - Background: Typical LED PT pair assembly
 - Paradox: How does a radiation tested pair of parts fail?
 - Hypothesis: Tests did not reflect application
 - New Test Results
- Anomaly Resolution
- Lessons Learned





What is WF/PC 2?

- WF/PC 2 is a CCD based imager aboard Hubble Space Telescope
- WF/PC 2 is the second generation wide field planetary camera







WF/PC 2 History

- WF/PC 2 was the "workhorse" camera from December 1993 to March 2002
- "Replaced" as the primary camera by the Advanced Camera for Surveys on SM3B but WF/PC 2 is still operational for science gathering
- WF/PC 2 will be replaced by WFC 3 on SM4






What Does WF/PC 2 Do?

- Investigate the composition, physical characteristics, and dynamics of celestial bodies
- Examine the formation, structure, and evolution of stars and galaxies
- Study the history and evolution of the universe
- Provide long-term spacebased research facility for optical astronomy

Camera	2-D imaging photometer
Spectral	1150Å to 10500Å
Range	Near UV to Near IR
Image	150" x 150" L-shaped field (0.1"/pixel)
	Simultaneous with 34"x 34" square field (0.046"/pixel)
Spectral Filters	48 total
Faint Targets	Limited by sky background (broad filters) or noise in readout electronics (narrow & UV filters) with RMS of 5 detected photons
Saturation	>53,000 detected photons/pixel (no safety issues)








PRC95-44a • ST Scl OPO • November 2, 1995 • J. Hester and P. Scowen (AZ State Univ.), NASA





The Nature of the Anomaly

- In the summer and fall of 2000, two anomalies in the read out of the shutter position encoders of WF/PC 2 forced the instrument into safe mode
- The encoders each consist of an LED – PT pair



- 7 years into a 5 year mission in an orbit of 28.5° at 598km
- Both shutters read as "closed"
- Further investigation of telemetry indicated 10 total errors over the 9 week period






Anomaly Investigation

- Anomaly Review Board initially identified
 12 possible faults
 - 8 mechanical faults were ruled out by analysis of flight telemetry
 - 2 electrical faults ruled out by flight telemetry
- All that remained:
 - Anomalous behavior of the LED
 - Anomalous behavior of the PT





Typical LED – PT Pair Assembly and a Paradox




•How does a radiation characterized pair fail?






New Hypothesis: Testing Fidelity

The test conditions did not accurately reflect the application.











PT Retest Results: Output Current (I_C) Degradation



0.E+00 1.E+10 2.E+10 3.E+10 4.E+10 5.E+10 6.E+10 7.E+10 8.E+10 9.E+10 1.E+11 63 MeV Proton Fluence (p/cm²)

Pair #2 Retest Results: V_{CE} & Rise Time







What does it all mean?

- In addition to the anticipated radiation degradation, the application degraded the operation of the LED – PT pair in a surprising way
- The combined effects of radiation and mechanical configuration lead to an unpredicted failure





Resolution of the Anomaly

- To correct the anomaly, a RAM patch was sent to the WF/PC 2 microprocessor to sample the PT after 10ms to ensure there was sufficient time to ramp up the PT
- No more anomalies






Lessons Learned

- Application specific configuration will affect inflight performance and ground based test results
- In addition to defining typical electrical performance, understanding the mechanical, thermal, and other physical conditions must be known in order to ensure test fidelity
- Close communication between the test engineers and all areas of the project is necessary to ensure appropriate radiation testing is conducted
- Not only must you fly what you test and test what you fly – you must also test the way you fly it





Supernova Remnant Cassiopeia A



Hubble Heritage

NASA and The Hubble Heritage Team (STScl/AURA) • Hubble Space Telescope WFPC2 • STScl-PRC02-15